


## SA1-01002 SwitchAir

For Rear Air Intake — Front (Port) Exhaust Switches



Delivers cool air to network switches with side air intake. Installs in minutes while network switch is live.



Delivers cool air to network switches with side air intake. Installs in minutes while network switch is live.

To match your network switches to the relevant Geist Cool SwitchAir product take a look at our compatibility chart at geistglobal.com

SA1-01002	Sp	ecific	ation
0/11 01002		001110	acioni

Rail Depth Range 27 5/8 to 29 5/8

Chassis/Insert Depth 7.63-11.63

Airflow

Switch Generated

(Passive)

Switch Intake/Exhaust

Rear/Front

Warrantv

Lifetime

Option L: Long Chassis Insert

10.63-14.63 Depth

Option S: Short Chassis Insert

5.75" - 8.5" Depth

## **Network Switch Cord Management**


STEP 1 Before installing SwitchAir; Velcro tie the network switch power cords to power supply handle toward the center of the switch. This will dress the switch power cords toward the center where the SwitchAir brush strip is located - allowing a good SwitchAir to switch seal. The SwitchAir brush strip has ample width to allow you to just direct the switch power cords toward the center. Power cords from one switch are allowed to pass through the brush strips of a unit below. Example shown of two networks switches would require two SwitchAir units.



## Installing SwitchAir

STEP 2 Before installing SwitchAir; remove the lower network switch mounting screw from each side of the rack front rails. Save these screws to be used in the next step for mounting SwitchAir. The network switch upper screw will remain fastened.

STEP 3 SwitchAir is in a fully extended position when shipped from the factory. Insert SwitchAir into the open rack space at the same U height as the switch. As SwitchAir is pushed into the space, the SwitchAir Rail Tabs will engage the network switch rails for support during installation. Keep pushing the SwitchAir into the space until the SwitchAir front mounting flanges are flush with the rack front rails. Reinstall the screws that were removed previously. Installation is now complete.





GM1176

800.432.3219

geistglobal.com

geistglobal.com

+44 (0) 1823 275100

Geist Asia